

MATERIAL SAFETY DATA SHEET

Page 2 of 2 CP-142

Section 8: Exposure Control and Personal Protection Information:

Respiratory Protection: none required under normal use.

Hand Protection: none required under normal use.

Eye Protection: none required under normal use.

Skin Protection: none required under normal use.

Section 9: Physical and Chemical Properties

CHARACTERISTICS:

Appearance:	Light green	Melting point:	n/a
Form:	Cylinder	Vapor pressure:	n/a
Odor:	Odorless	Vapor density:	n/a
Solubility in Water:	Insoluble	Evaporation rate:	n/a
Bulk density:	n/a	Boiling point:	n/a

Section 10: Stability and Reactivity

Conditions to avoid: none

Materials to avoid: none

Stability: Stable

Hazardous decomposition products: CO and CO₂ and other decomposition products when burned.

Section 11: Toxicological Information:

None

Section 12: Environmental / Ecological Information

None

Section 13: Disposal Consideration

Used OPC drums should be disposed of or recycled in an environmentally safe manner and in accordance with governmental regulations. Disposal regulations vary from locality to locality, therefore consult your local Lanier office or the EPA to determine the proper method for disposal. Used drums can be sent back to Lanier Worldwide, Inc. in Atlanta, Georgia, USA, for recycling.

Section 14: Transportation Information

None. This is not a hazardous product.

Section 15: Regulatory Information

None

Section 16: Miscellaneous Information

Judgment as to the suitability of information contained herein for user's purposes is the responsibility of the purchaser. Therefore, although reasonable care has been taken in the preparation of this information, Lanier Worldwide, Inc. extends no warranties, makes no representations, and assumes no responsibility as to the accuracy or suitability of such information for application to user's intended purposes or for consequences of its use. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we do not guarantee that these are the only hazards that exist.